

Summary of Soil Vapor and Soil/Groundwater Screening Sample Results
Cabo Rojo Groundwater Contamination Site
Cabo Rojo, Puerto Rico

current as of 5/8/2013

No.	PSA Location	Vapor Results	Soil/GW GC Screening Results	Depth to GW (feet bgs)	Soil Delineation Sampling Recommendations
1	Extasy Q Prints		PCE/TCE detected in locations 01 to 05; ND 06 to 10; highest PCE 62.71/TCE 13.11 at SB-05. No GW samples collected.	unknown - refusal between 2 and 8 feet.	Figure shows 6 recommended boring locations for soil delineation sampling.
2	Cabo Rojo Professional Dry Cleaners		PCE/TCE detected in nearly all soil samples, highest at CB-SB-05A (0-2); GW PCE and TCE detected	10 to 12 feet	Figure shows 6 recommended boring locations for soil delineation sampling.
3	D'Elegant Fantastic Dry Cleaners (1)	EPA: vapor detections at south end of former dry cleaner building (now razed and replaced by Walgreens)	Very few detections of PCE/TCE in soil in similar locations as the vapor testing; GW had a few TCE detections	approximate-ly 14 feet	Figure not created. Soil may have been disturbed/moved during construction of Walgreens. Recommend one or two borings in southern area (DE-SB-01 area - SW corner of former building)
4	Serrano II Dry Cleaners		PCE/TCE in most soil samples boring 01 to 06; 07 & 08 ND. GW PCE detected.	approximate-ly 10 feet	Figure shows 6 recommended boring locations for soil delineation sampling.
5	PRIDCO East	PCD detected in 2 samples; majority ND	collecting samples 5/13-14	TBD	TBD
6	PRIDCO West Building #1	PCE/TCE detected in 5 samples	collecting samples 5/7-8	TBD	TBD
6	PRIDCO West Building #2	PCE detected in all smaples	collecting samples 5/9-10	TBD	TBD
7	RETO Plant	PCE/DCE detected in 4 samples	No samples collected		
8	Raul Lugo	PCE detected in 6 samples	No samples collected		
9	Unfinished Strip Mall	PCE/DCE detected in 6 samples	No samples collected		

Notes:
(1) Current location of Walgreens